Fotec AG Eigenheimstr. 22 CH-8700 Küsnacht
P.O.Box 1123 Switzerland
Phone: ++41 1 913 30 00 Fax: ++41 1 910 45 25
e-mail: info@fotec.ch www.fotec.ch

TECHNICAL INFORMATION Küsnacht, Dec. 1999 (rev. 2/03)

FOTECOAT 1930 K

Direct ceramic printing on tiles in single, double and third fire.

1. Description

- Dual-cure diazo/polymer screen process emulsion for printing on ceramic substrates and for ceramic decalcomanias.
- Suitable for most ceramic inks.
- The sensitizer can be mixed directly into the FOTECOAT 1930 K emulsion (dissolving in water is not necessary).
- The emulsion can be post-exposed to reach complete thru-curing.
- Possibility to harden chemically with FOTECHEM 2100 to produce permanent stencils.
- Blue, high contrast colour to facilitate touch-ups.
- FOTECOAT 1930 K is already light sensitive; the following sensitising with the diazo powder should be done under yellow light only.
- FOTECOAT 1930 K is phthalate-free.

2. Application advantages

- After sensitizing approx. 46% solids content.
- Medium viscosity, suitable for meshes from 43-80 to 120-34 threads per linear cm and for manual or machine coating.
- The diazo sensitise is supplied in a separate, airtight, humidity repellent and heat-insolating sachet. It can be added directly to FOTECOAT 1930K; it dissolves quickly and under light stirring. Before coating let the emulsion degas.
- High resolution with excellent mesh bridging.
- Can be decoated with the usual chemicals as long as a catalyser has not hardened the stencil.
- If necessary, FOTECOAT 1930 K can be diluted with a small amount of water.

3. Stencil quality

It is advisable to treat the mesh prior to coating with an abrasive and degreasing paste like FOTECHEM 2023; at least the screens should be degreased thoroughly.

Mesh	Coating	Stencil build-up
43-80	1/1	25 µ
77-55	1/2	16 µ
120-34	1/1	6 µ
120-34	1/2	10 µ

- Intermediate drying and post-coating improve the Rz-value.
- The stencil surface is semi-mat and has no tendency to get sticky.
- The stencil should be completely dry before exposing; for drying never use heat over 40°C.
- Control stencil humidity with the FOTECO AQUATEST device.

4. **Storing**
   - Unsensitized at 18 - 25°C : 1 year
   - Sensitized at 10-15°C : 2 months
   - Sensitized at 20-25°C : 1 month
   - Pre-coated screens, kept in the dark at 20°C: 3 weeks

5. **Exposure**
   5 KW MH at 100 cm distance and 100 operating hours, with photopolymer bulb:

Coating	Mesh	Time in seconds after complete drying
1/1	43-80 white	65
1/2	43-80 white	85
1/1	43-80 yellow	100
1/2	43-80 yellow	130
1/1	77-55 white	50
1/2	77-55 white	65
1/1	120-34 white	35
1/2	120-34 white	45
1/1	120-34 yellow	50
1/2	120-34 yellow	65

6. **Decoating**
   - Standard stencil decoating chemicals can be used.
   - The decoating chemicals should never dry on the stencil.
   - Make sure the screen filler is dissolved first with water before decoating starts.
   - Whenever possible degrease before the decoater is being applied; this facilitates decoating and helps to prevent ghost pictures. FOTOCHEM 2033 is an ideal degreaser concentrate.
   - For the regeneration of the decoated mesh FOTECHEM 2080/2085 can be used to remove all ink and emulsion residues; jet wash is necessary.
   - Diazo stains can be bleached out after decoating with FOTECHEM 2075.
   - **Important: A fully exposed stencil, with full thru curing, or a post-exposure, facilitates the stencil removal.**

FOTEC AG